

RETROFIT

Date: April, 2014

PRODUCTS AFFECTED: SSX2733; SSX2749; SSX2765
AND SSX2818 EPIQ GRILLS

HAZARD:

ACCUMULATED GREASE CAN CATCH FIRE

If the grease pan is not installed or cleaned properly, grease may accumulate and catch fire.

ACTIONS:

Please instruct any customers who have the above listed EPIQ grills to review the attached instructions showing proper installation of the grease pan and drip pan. Also, have them install the enclosed label per the attached instructions as a reminder. (Label Shown Below)



WARNING



Accumulated Grease Can Catch Fire

- Ensure grease pan is installed correctly, read and follow installation instructions
- Clean grease from grease pan after each use
- Empty grease from drip pan after each use



Grease Fires Can Cause Burns and Property Damage

QUESTIONS:

If you have questions on this advisory or need assistance contact: [Dan Voelz at \(262\) 656-6073](mailto:Dan.Voelz@snapon.com)