PRODUCT SAFETY

Snap-on Incorporated

RECALL

October 1, 2014

PRODUCTS AFFECTED:

PART NUMBERS & DESCRIPTION:

WE200A, WE250A, HRC1401340 and HRC4403211

Torch Kits and Handles manufactured by Harris Products between December 1, 2013 and May 31, 2014.

HAZARD:

There is a potential of oxygen and fuel leakage which may result in fire hazard, severe personal injury and loss of service.

ACTIONS:

- 1. Do not use torch kits or handles purchased between December 1, 2013 and May 31, 2014.
- 2. Return the entire torch kit with the RMA form completely filled out to the following address:

ASC, Inc. 1677 Oakbrook Drive Suite B Gainesville, GA 30504

3. A replacement will be shipped free of charge to the address that entered on the RMA form sent with the returned product.



WE200A and WE250A



HRC1401340



HRC4403211

QUESTIONS:

If you have questions on this advisory or need assistance contact: Mike DeKeuster - 262-656-6677

IMPORTANT SAFETY NOTICE

Harris Products Group and Lincoln Electric **Welding Torch Handles**

Models 18-5 and 85, Sold between December 2013 and May 2014

Consumers should check their torch handles if they have one of the above All potentially-affected torch handles are stamped with the model number and one of the following manufacturing date codes: FM, GA, GB, and GC. Both the model number and the date code are stamped into the torch handle at the end opposite to the valves. (Units with "O" above "Harris" and to the right of the rivet head are not included in this recall.)







Date Code



Location of Stamp

These models were sold both individually and as part of an outfit (including hoses, tanks, regulators, and other component parts).

HAZARD

THE TORCH HANDLES CAN LEAK OXYGEN OR FUEL AND CAUSE A FIRE HAZARD

If you have an affected torch handle call the number below for a free replacement.

1.800.447.6906

Monday - Friday, 8am-5pm EST or visit http://www.harrisproductsgroup.com/recall/



Instructions for Confirming that Your Torch Handle is Being Recalled

This recall involves the following models:

- o Model 18-5
- o Model 85

All of the potentially-affected torch handles are stamped with the model number and one of the following manufacturing date codes: FM, GA, GB, and GC. Both the model number and the date code are stamped permanently into the torch handle at the end opposite to the valves.







Date Code



Location of Stamp

These models are sold both individually and as part of an outfit (including hoses, tanks, regulators, and other component parts).

If you have one of the affected models, please visit our website at http://www.harrisproductsgroup.com/recall or contact Harris Products Group toll-free at 1.800.447.6906 from 8:00 a.m. to 5:00 p.m. EST – Monday through Friday to participate in the recall.

TO EASILY IDENTIFY PRODUCT THAT WAS MANUFACTURED BY HARRIS AFTER MAY 15, 2014, AND IS NOT PART OF THE RECALL, WE HAVE CHANGED OUR PACKAGING LABELS.

Please see below for the before and after images to help you identify new product.

OUTFITS

OLD LABELING PRIOR TO 05/15/2014











NEW LABELING AFTER 05/15/2014



PORT-A-TORCH'S





OLD LABELING PRIOR TO 05/15/2014







NEW LABELING AFTER 05/15/2014



TORCH HANDLES













NEW LABELING AFTER 05/15/2014



PRODUCT RECALL NOTICE



Turn to the THE HARRIS PRODUCTS GROUP Pros

TO EASILY IDENTIFY PRODUCT THAT WAS MANUFACTURED BY HARRIS AFTER MAY 15, 2014, AND IS NOT PART OF THE RECALL, WE HAVE CHANGED OUR PACKAGING LABELS.

Please see below for the before and after images to help you identify new product.

Welding and Cutting Outfits

WE250A OLD LABELING PRIOR TO 05/15/2014







WE200A OLD LABELING PRIOR TO 05/15/2014







PRODUCT RECALL NOTICE



RMA #: SNAPON0515

THE HARRIS PRODUCTS GROUP PRODUCT RECALL FORM

Distributor Name:	
Contact Person:	
Contact Email:	
Contact Phone:	
Address:	

Part Number	Description	Qty. Returned

Return completed form and recalled product to:

ASC, Inc. 1677 Oakbrook Drive, Suite B Gainesville, GA 30507

Please do NOT return recalled product to our facilities in Gainesville, GA or Mason, OH facilities.